




# Surface Mount USB

## INSTALLATION INSTRUCTIONS

Part#: USBSM-AC-BK


### PARTS/TOOLS NEEDED:

		
Surface Mount USB	Drill & Drill Bit	Screws (Not Included)

### IMPORTANT SAFETY INSTRUCTIONS. READ CAREFULLY FOR YOUR PROTECTION AND SAVE ALL INSTRUCTIONS.

- Disconnect power before installing, adding or changing any component.
- To avoid a hazard to children, account for all parts and destroy all packing materials.
- It is recommended that fuse protection be added to the positive (+) input.


1. Determine the installation location for your charger and mark the location of the holes needed. Center the wire exit hole between two screw holes.
2. Pre-drill a 1/4" hole for the wires.<sup>1</sup> Pre-Drill two 1/8" holes<sup>2</sup> for your mounting screws.



3. Use the screws to attach the charger housing to the desired location.



4. Wire the charger following the wiring diagram below.



3030 Corporate Grove Dr.  
Hudsonville, MI 49426  
Phone: 616.396.1355  
[itc-us.com](http://itc-us.com)

For warranty information please visit [www.itc-us.com/warranty-return-policy](http://www.itc-us.com/warranty-return-policy)  
DOC #: 710-00220 · Rev A · 4/18/2023