## Nova<sup>™</sup> Scene Light

Part#: 69770-FF-KK


PARTS/TOOLS NEEDED:			
	M	Screws Provided	Butt Splices & Application Specific Sealant (Not Provided)
Nova™ Scene Light	Power Drill (Not Provided)		

## IMPORTANT SAFETY INSTRUCTIONS. READ CAREFULLY FOR YOUR PROTECTION AND SAVE ALL INSTRUCTIONS.

- $\cdot$  Disconnect power before installing, adding or changing any component.
- $\cdot$  To avoid a hazard to children, account for all parts and destroy all packing materials.
- It is recommended that fuse protection be added to the positive (+) input.
- 1. Determine the installation location and drill hole for wires then align the light with gasket in the wire hole and use the light to mark screw holes. Drill appropriate sized holes for mounting screws.



2. Follow the wiring diagram below to wire the light to your system.



3. Feed the wires back through the hole and use application specific sealant in the specified circles areas both below and on top of the rubber. NOTE: Be sure the sealant does not block the heat sink channels.



4. Press the light onto the rubber gasket then screw the light in place.



4. Place the bezel on the light and push until it snaps into place.





3030 Corporate Grove Dr. Hudsonville, MI 49426 Phone: 616.396.1355 **itc-us.com** 

For warranty information please visit www.itc-us.com/warranty-return-policy DOC #: 710-00147 · Rev A · 11/09/2022